

A 5x5 grid with a small cluster of black dots in the top-left area.

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY


Indian Agency ~~REDACTED~~ ~~REDACTED~~

CONCLUSIONS

Allottee ~~XXXXXXXXXX~~

Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	 RECEIVED MAR 18 1956 JLG
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

██████████ 19██████████

Well No. 2 is located 300 ft. from N line and 300 ft. from W line of sec. 36

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Disputed ground
(Field)

(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5000 ft. 0.2

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 10 Jns. (1958) 1st 3-25 - 1st egg @ 1595 w/30 min 21 gpt + 1st Fertilite per
week + 50 min week - 10 Jns. 3-23-59. WOC 24 hrs - 2nd 51st egg. w/1000, 15
min, w/all hatched - OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Regatta's Performance Company

Address P.O. Box 200

By

Title