

(SUBMIT IN TRIPLICATE)

Indian Agency Indio

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. _____

11-21-61-32

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 21, 1959

Location

Well No. 5-2 is located 660 ft. from [N] line and 130 ft. from [W] line of sec. 20

11/24, Sec. 20
(1/4 Sec. and Sec. No.)

1-31E
(Twp.)

1-11W
(Range)

N. 1. P. 1.
(Meridian)

Verde Valley
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5647 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth - 2600' Run logs: Top of "A" layer - 1796'
11- 83 joints, 2590' of 1 1/2" casing, at 2590' with 50 sacks cement
P.T. - 9400 A.T., 1 V tool set at 1796' with 50 sacks
Top of cement, 1st stage, 2180'
Moved in Cable tool, filled cement - 8/10/59
Tested for two hours with 500# pressure.
Pipe okay.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Astec Oil and Gas Company

Address Box # 786,

Farrington, N. Mex.

By ORIGINAL SIGNED BY JOE C. SALMON

Title District Superintendent