

(SUBMIT IN TRIPLICATE)

Indian Agency Ignacio

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. _____

11-20-50-32

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
AUG 24 1959
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

August 21, 1959

Ute Indian

Well No. 30 is located 660 ft. from N line and 330 ft. from W line of sec. 20

NW/4, Sec. 20
(1/4 Sec. and Sec. No.)

T-31N
(Twp.)

R-14W
(Range)

S. 100.0
(Meridian)

Verde Valley
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5617 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth - 871h'
Sand-oil fraced with 35,000 Gallons oil and 10,000# sand
Breakdown pressure - 1200#
Treating pressure - 1000#
I.P. - 42 bps
Run 31 joints 2 3/8" tubing lands at 2502'
Run Pump and rods.

RECEIVED
AUG 25 1959
OIL CON. COM.
DIST. 3

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Aston Oil and Gas Company

Address Box # 706,

Farmington, N. Mexico

ORIGINAL SIGNED BY JOE C. SALMON

By Joe C. Salmon

Title District Superintendent