

(SUBMIT IN TRIPLICATE)

Indian Agency **Consolidated Ute**

x		
	21	

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee **14-20-604-83**

Lease No. **Ute Mountain**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	x
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 8, 1960

Well No. **12** is located **550** ft. from **N** line and **1980** ft. from **W** line of sec. **21**

NW/4 Sec. 21 (1/4 Sec. and Sec. No.)
31N (Twp.)
14W (Range)
NMB&N (Meridian)
Verde-Gallup (Field)
San Juan (County or Subdivision)
New Mexico (State or Territory)

G.L.

The elevation of the ~~derrick floor~~ above sea level is **5727** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud 8:30 PM, 8/5/60
Cemented 5 fts. of 8-5/8" casing at 107' w/80 sx treated w/2% CaCl.
Plug down 5:10 AM, 8/6/60. Good cement returns to surface.
Tested 8-5/8" with 800 psi for 30 minutes; held ok.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Socony Mobil Oil Company, Inc.**

Address **P. O. Box 3371**
Durango, Colorado

By **P. M. Barry**
District
Title **Prod. Supt.**

REVISED

June 11, 1954

Very Respectfully,
John F. Kennedy

John F. Kennedy