

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices a	nd Reports on Wells
	5. Lease Number
	14-20-603-2022
1. Type of Well	6. If Indian, Allotee or Tribe name
X Oil Gas Other	Navajo
2. Name of Operator	7. Unit Agreement Name
Vantage Point Operating Company	Horseshoe Gallup
3. Address & Phone No. of Operator 2401 Fountain View Drive	8. Well Name & Number HGU #86
Suite 700	9. API Well No.
Houston, TX 77057-4862	30-045-10651
(713) 780-1952	10. Field and Pool
4. Location of Well, Footage, Sec., T, R, M	Horseshoe Gallup
C-24-31N-17W	11. County and State
788' FNL & 1869' FWL	San Juan, New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA	
. , , , , , , , , , , , , , , , , , , ,	ype of Action
Abando	
X Notice of Intent Recomp	
Plugging	
Subsequent Report Casing	
Altering	· · · · · · · · · · · · · · · · · · ·
Final Abandonment Dispose	
X Other -	LTSI
13. Describe Proposed or Completed Operations	
This well is currently shut-in.	
Vantage is requesting LTSI status from the BLM until such time it is	
economically feasible to return this well to produ	until such time it is of JUL 22 BI
SEE ATTACHED FOR	
Vantage is requesting LTSI status from the BLM until such time it is economically feasible to return this well to production. SEE ATTACHED FOR CONDITIONS OF APPROVAL AUG 0 1 1995	
CONSTRUME OF APPROVAL AUG 0 1 1995	
THIS APPROVAL	
THIS APPRISANCE	N N
	- 10
14. I Hereby certify that the foregoing is true and correct.	
Signed Diamon TK Aburburt Title (Consulting Engineer Date 7/13/1994
(This Space for Federal or State Office Use)	
APPROVED BY: Title	Date
CONDITION OF APPROVAL, if any:	
	40000

SEP 201994