

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____
Window Rock _____
Allotted _____
Lease No. 11-20-603-28 3531

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF CONVERTING to water injection

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

MARCH _____, 19 63

HORSESHOE GALLUP UNIT

Well No. 89 is located 600 ft. from N line and 600 ft. from W line of sec. 19

19 19 Sec. 19 31N 16W NMPM
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Horseshoe Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the ~~derrick~~ ^{Ground} floor above sea level is 5607 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Moved in pulling unit. Pulled rods and tubing. Ran Baker Model "A" Tension Type packer set at 2424' on 2" EUE 8R 4.7# J-55 tubing on 2-6-63.

Started injecting water into Upper Gallup ~~thru casing and into Lower Gallup~~ thru tubing on 3-28-63.

"Effective May 3, 1966, The Atlantic Refining Company changed its name to Atlantic Richfield Company"



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Atlantic Refining Company

Address P. O. Box 2197

Farmington, New Mexico

By B. J. Sartain

Title Production Supervisor