



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Carlsbad  
Lease No. 87 07015  
Unit Acidizer

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

OCT 6 1959

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

Well No. 43 is located 1100 ft. from S line and 50 ft. from W line of sec. 13  
Section 13 (1/4 Sec. and Sec. No.) T-11N (Twp.) Range (Range) Meridian (Meridian)  
Cliffs (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5229 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth - 2300'  
Circulator (well) with 1,000 bbls. water and 50,000 # sand, & 100 rubber ball sealers  
Break down pressure - 2000#  
Circulator pressure - 1300#  
Final pressure - 200#  
I.B. - 13.8 bps  
Set 108 joints, 2698' of 2" tubing, landed at 2705'  
Shut in for gauge.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Acidizer Oil and Gas Company  
Address Box 1735, Farmington,  
New Mexico  
By Joe C. Salmon  
Title District Supervisor

