

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Carlsbad
Lease No. 5 37325
Unit Coaler

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED
OCT 6 1959
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 2, 1959

Well No. 10 is located 1100 ft. from S line and 240 ft. from W line of sec. 18

10 (1/4 Sec. and Sec. No.) 2-11N (Twp.) 11-11W (Range) 10-11-11 (Meridian)


10 (Field) San Juan (County or Subdivision) 10-11-11 (State or Territory)

The elevation of the derrick floor above sea level is 5129 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth - 2500'
Run logs: Top of Pictured Cliffs - 2455'
perforated 2455-2700, with 1/2" shots per foot
Set 37 joints, 2712' of 1 1/2" casing at 2733' with 1/2" shots cement
Top of Cement - 2177'
Sealed hole dry
Tested 2 hours with 500# pressure
Pipe Okay



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Isaac Oil and Gas Company

Address Box 277, Farmington,

New Mexico

ORIGINAL SIGNED BY JOE C. SALMON
By _____

Title Joe C. Salmon

