

(SUBMIT IN TRIPLICATE)

Indian Agency Ignacia

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 11-22-151-146

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	<u>May 29 1959</u>
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 25, 1959

Well No. 1 is located 143 ft. from N line and 120 ft. from E line of sec. 15
NE/4, Section 15 (1/4 Sec. and Sec. No.) 11-22-151 (Twp.) 11-22-151 (Range) 11-22-151 (Meridian)
Verde Valley (Field) San Juan County (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth 86. Run logs: Top of sand lookout 271, sand 717, 1125, 1276. Set 1276' of 1 1/2" casing at 1106 with 65 cu. cement. Top of cement at 1125'. Set two-stage cement collar below saltwater marker at 1125' and cemented with 65 cu. cement. Top of cement at 720'.

Work in cable tool. Rilled cement 5/22/59. Tested for 2 hours with 500' pressure - pipe okay.

I understand that this plan of work must receive approval of _____

Company AMERICAN OIL COMPANY

Address Box 736

San Juan County, New Mexico

ILLECIBLE

announced.

By L. M. STEVENS

Title MANAGER