Form 9-331 b (April 1952)

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Indian Agency Scancollanded Uto Imacio, Colerado.... Allottes Mountain Uto Tripo Lease No. 14-20-604-119

NTICE OF INTENTION TO DE	RILL.		T REPORT OF WATER SHUT-OFF		K
OTICE OF INTENTION TO CH			IT REPORT OF SHOOTING OR ACII		
OTICE OF INTENTION TO TE		SUBSEQUEN	IT REPORT OF ALTERING CASING		-
OTICE OF INTENTION TO RE			IT REPORT OF REDRILLING OR R	EPAIR	- -
OTICE OF INTENTION TO SH		SUBSEQUEN	IT REPORT OF ABANDONMENT		
OTICE OF INTENTION TO PU		SUPPLEMEN	ITARY WELL HISTORY		
OTICE OF INTENTION TO A					-
				RECEIVED JUN 29	七〇
	(INDICATE ABOVE BY CHEC	K MARK NATURE OF REPO	RT, NOTICE, OR OTHER DATA)	-CE!	1
				REGIE	1957
		Auton Tr	er Merrico	19 129	1951
		Second in		2011	4.61 Dog
Mountain II	te		. 660 (E)	1:£ 18	· •
ll No. 18.9	_ is located _1990	$_{\rm ft.}$ from $_{\rm S}$ line a	and 660 ft. from	line or sec	L
		(-)		for	
mieni sec.	18 31]	E IN V	Meridian)		
(14 Sec. and Sec. No.)	(Twp.)	(results)	(meres 100 mm)		
Yerde-Gally		an Jum County	(State or	Torright	
(Field)	round level	(County or Subdivision)	(Dance Of	SOTT A	
ne elevation of the o	Annie Ante	sea level is SAC	k ft.	ati tivin	
ne elevation of the c	EXPERIENCE ADDIVE	; SCA ICYCI IS 1-4000		KILLIU	1
		DETAILS OF WO	ORK -	24.057	1
ي -				JUN 21 557	nent
tate names of and expected	depths to objective sands ing points	;; show sizes, weights, and , and all other important		IL CON. COM	
			10		
Shacooc: 1	Nume 12, 1957.			DIST. 3	
			•		
CASING INTA	LILBI				
	a - 10m		halled-out hottom	totalling 96	.01.
	8 5/8" 00 204	N-B CHETHER AL.	belled-out bottom"	,,	-
Ran 3 jts.	109.13' from KI	3 .			
Ran 3 jts. Landed at 3					ė in
Lunded at 1		r. 20 sex selet	Al, 4 DEEK CHC/K; A	57.6 S.). General	4 646
Landed at 1	/80 sex regular		and the second s		
Landed at 1	/80 sex regular 00 6:07 FM, 6-3	12-57. No trou	ble.		
Commented/2, casing. W	OC 6:07 396, 0-1	ra-21. No grou	ble.		
Commented/2, casing. W	OC 6:07 396, 0-1	ra-21. No grou	ble.		
Commented/2, casing. W	/80 sex regular OC 6:07 PM, 6-1 ing to 1000f.	ra-21. No grou	ble.		
Committed/2, casing. W	or 6:07 m, 6-3	Test CK.			
Committed/2, casing. W Tested cas	or 6:07 m, 6-3	Test CK.	Geological Survey before operati		ed.
Committed/2, casing. W	or 6:07 m, 6-3	Test CK.			od.
Compared 2, casing. W. Tested cas:	or 6:07 m, 6-3	Test CK.			ed.
Compared A. Compared A. Compared A. Compared Com	ing to 1000%.	Test CK.			od.
Committed/2, casing. W Tested cas	or 6:07 m, 6-3	Test CK.			sd.
Committed/2, casing. We Tested cas: I understand that this plant.	ing to 1000%.	Test CK.			sd.
Committed/2, casing. We Tested cas: I understand that this placement.	ing to 1000%.	Test CK.			od.
Comented/2, casing. We Tested cas:	ing to 1000f. In of work must receive to PURCO PHENOL.	Test CK.			od.

