


1952,



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R359.4.
Approval expires 12-31-60.

Indian Agency San Juan

Allottee _____

Lease No. 11-02-00-110

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

MAR 26 1957

U. S. GEOLOGICAL SURVEY
NEW MEXICO

Well No. 11-5 is located 1000 ft. from N line and 600 ft. from W line of sec. 18

San Juan (4 Sec. and Sec. No.) San Juan (Twp.) San Juan (Range) San Juan (Meridian)
San Juan (Field) San Juan (County or Subdivision) San Juan (State or Territory)

The elevation of the ground above sea level is 5000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)

Spudded 2-23-57.

Set 3 1/2" 25.40', 3 1/2" 2-40 35.40' & set the csg w/ Millwrights collar. Landed at 111.10' from RL.

Cemented w/ 20 sac regular cement, 20 sac oilwell, & 20 sac oilwell cement in 4 strings. Good cement returned. Plugged w/ 1000 - 1000 27' of cement in pipe.


WSS at 2:30 A.M. 3-25-57. Tested to 500'. Test OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Juan Petroleum Company

Address 106 West Street
Alamo, New Mexico

By E. H. [Signature]
Title Eng. Asst. Mgr.



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency [REDACTED]

[REDACTED]

Allottee -----

Lease No. 44-100-112

●			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 21-3 is located 1,000 ft. from [N] line and 600 ft. from [W] line of sec. 24

(34 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

(Field) _____
(County or Subdivision) _____
(State) _____

The elevation of the ~~surface~~ above sea level is ~~200~~ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging, logging points, and all other important proposed work)

CLASSIFICATION: 1-30-97

Don't let this one go! Get this 2-35 15-36 5/8" casing w/ heavy galvanized steel.
 Located at 1000 10th St.

Respectfully,
 [Signature]

Box 1 Below shows two containers at 240, 243 and 242.

Counted with 30 sec. exposure, 20 cm. f.l. microscope, 45 gill in 5 minutes.
Circulation good. WBC 20,000 P.B.

Tested Working on 12/24/2004. Test OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company XXXXX XXXXXXXXXXXXXXXXXXXXXXX

Address: 206 West Camden

By

Title