

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency **Mountain Ute**
Agency **Montezuma, Colorado**
Allottee **Mountain Ute Tribe**
Lease No. **14-22-22-112**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED

NOV 19 1957

U. S. GEOLOGICAL SURVEY
MONTICELLO, NEW MEXICO

Well No. **14-23** is located **600** ft. from **[S]** line and **1000** ft. from **[E]** line of sec. **10**
14 (4 Sec. and Sec. No.) **11N** (Twp.) **14W** (Range) **R.14-P.14** (Meridian)
Yukon Valley (Field) **San Juan** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the **ground level** above sea level is **5700** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud November 18-, 1957

CASING HEADS:

Run 3 Jcs., 55.30', 8 5/8", 24, 274, 274 casing w/balled out bottom joint welded top to bottom. Landed 1' below GL; total 207' 10".

Cemented w/100 sac regular cement. Circulated about 10 min. WTS at 9:00 P.M., 11-20-57.

Fractured casing to 1000 yards. Test OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations are commenced.

Company **FRANK FARMER COMPANY**

Address **204 West 2nd**

Albuquerque, New Mexico

By

Title

