

(SUBMIT IN TRIPLICATE)

Indian Agency Luna

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee 1-29-11-46

Lease No. \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED  
U. S. GEOLOGICAL SURVEY  
FARMINGTON NEW MEXICO

Ute Indian # 2-C July 19, 1959

Well No. 1 is located 1025 ft. from N line and 700 ft. from W line of sec. 1

SW 1/4 Sec. 1 N 1 E (1/4 Sec. and Sec. No.) T-22N (Twp.) R-10W (Range) 114-1-1-46 (Meridian)  
Verde Valley (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5739 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded 7/6/59. Set 3 jts. 10' of 7 5/8" casing at 111' with 20 sacks of cement. Plug down 7/15/59.  
Leaked casing with 500# pressure for 30 minutes, no leaks.  
Drilled cement plug 7/17/59, tested for 30 minutes with 500# pressure - no drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Astec Oil and Gas Company  
Address Box 786  
Farmington, New Mexico  
By Joe C. Salmon  
Title District Supervisor

