

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau No. 42-E388.4.  
Approval expires 12-31-60.

Land Office Santa Fe  
Lease No. 87-076115  
Unit Greaser

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Greaser

April 12

, 19 60

Well No. 10- is located 1460 ft. from [N] line and 1190 ft. from [E] line of sec. 18

SW 1/4 Section 18

(1/4 Sec. and Sec. No.)

31N

(Twp.)

11E

(Range)

S.W.P.M.

(Meridian)

Undersaturated Pictured Cliffs

(Field)

Sac. Juan

(County or Subdivision)

New Mexico


(State or Territory)

The elevation of the derrick floor above sea level is 6169 ft. S.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded 4/8/60  
Set 3 Jts., 55' of 8 5/8" surface casing, landed at 109'  
with 70 sacks cement  
Tested casing with 500# pressure for 30 minutes.  
No leaks.  
Drilled cement plug 4/14/60  
Tested with 500# pressure for 30 minutes  
No drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Astec Oil & Gas Company

Address Box # 706, Farmington

New Mexico

ORIGINAL SIGNED BY JOE C. SALMON

By Joe C. Salmon

Title District Superintendent

ALL  
1950