Form	9-331 a
(Feb	. 1951)

ı			
ı	1		
ı	 		
ı	, '		
ı		1	
ı			
1	1		
1	 		
		1	

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	Santa Po
Lease No.	076095
Unit Cas	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

	May 1	9 , 19.61
Well No. 8 is located	1030 ft. from $\begin{bmatrix} N \\ S \end{bmatrix}$ line and 113	ft. from $\frac{E}{E}$ line of sec. 18
NE Section 18	31-8 11-4 N.M.1	P.M.
(¼ Sec. and Sec. No.)		Meridian)
Besin Dekota	Sen Juan	New Martin
(Field)	(County or Subdivision)	(State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 5-16-61, Total Depth 3104'.

Ran 77 joints 9 5/8" 36# casing (3089')

set at 3102'. Commuted with 450 sacks regular,

% gel, 1 cu.ft. Strata-Crete"6"/sk. and 50 sacks

Rest. Held 1500#/30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company	R) Paso Matural Gas Company	
Address	Box 990	
	Persington, Dev jonico	By Original Signed D. W. Mechan
		Title Petroleum Engineer