

(SUBMIT IN TRIPLICATE)

Indian Agency Ute Indian

	17	

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Ute Mountain Tribal
Contract No. 11-20-601-82
Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
DEC 24 1958
GEOLOGICAL SURVEY
SANDWICH, NEW MEXICO

December 22, 1958

Well No. 3-17 is located 780 ft. from N line and 2110 ft. from E line of sec. 17
NE/4, NW/4, Sec. 17 T-31N R-21W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Verde Gallup San Juan County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6019 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1. Ran 6 1/2 joints 5 1/2", J-55, 15.5#, casing on September 30, 1958. Casing landed at 2638 R.L.B. Cemented w/100 sacks regular w/2% gel. Set Baker Stage Collar at 1745' R.L.B.
2. Cemented second stage thru Baker Stage Collar w/50 sacks regular w/2% gel on September 30, 1958.
3. Ran temperature survey on October 1, 1958. Top of cement 1390' R.L.B.
4. Ran 8 1/2 joints 2", 4.7#, J-55 tubing on October 6, 1958. Landed at 2597 O.L.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Southern Union Gas Company

Address 1001 Burt Building

Dallas, Texas

By Paul J. Clute

Title Drilling Superintendent

