5. LEASE 14-20-603-2022

Form 9-331 Oec. 1973

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Navajo
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	Horseshoe Gallup Unit
reservoir, Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil — gas —	Horseshoe Gallup Unit
well — well — other X - Injection	9. WELL NO.
2. NAME OF OPERATOR ARCO Oil & Gas Co., Div. of	73
Atlantic Richfield Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR 707-17th Street,	Horseshoe Gallup Unit
P.O. Box 5540, Denver, CO 80217	11. SEC., T., R., M., OR BLK. AND SURVEY OF
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	AREA .
below.) Unit "H"	Sec. 14-31N-17W
AT SURFACE: 2080' FNL & 660' FEL, Sec. 14	12. COUNTY OR PARISH: 13. STATE
AT TOP PROD. INTERVAL: Appx. same	San Juan New Mexico
AT TOTAL DEPTH: Appx. same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	None Assigned
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	5597' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF 🔲 🖳	
FRACTURE TREAT	EIVED DEGEIVER
SHOOT OR ACIDIZE U F. E. C. I	(NOTE: Report realise of multiple completion or zage
PULL OR ALTER CASING	2 0.1983 change on Form HAN 06 1984
MULTIPLE CUMPLETE 1 1 1	· · · · · · · · · · · · · · · · · · ·
CHANGE ZONES BUREAU OF LA	RESOURCE AREA OIL CON. DIV.
(other)	\DIST. 3
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	a all postinent details, and the pertinent dates
including estimated date of starting any proposed work. If well is di	irectionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones pertinen	t to this work.)*
ARCO has plugged and abandoned the subject well	
Notice dated December 30, 1982, and approved by	y the BLM-MMS on January 13, 1983.
	Gallup fm. Spotted cement plugs
as per the attached plugging operations report	
Completed P & A, $10-5-83$.	
	•
Final restoration will be commenced as soon as	
subsequent report will be filed when restoration	on has been completed.
Subsurface Safety Valve: Manu. and Type	Sat @ Ft
Substitute Safety valve, manu, and Type	
18. Thereby certify that the foregoing is true and correct	
SIGNED Stephen Rase TITLE Dist. Prod. Sup	ot. November 30, 1983
(This space for Federal or State off	ice use)
APPROVED BY	DATE
CONDITIONS OF APPROVAL, IF ANY:	J. 110

HORSESHOE GALLUP #73, Horseshoe Gallup Field

P & A OPERATIONS:

MI RU. Rel'd pkr. Pull tbg. RIH OE & spot 20 sx plug across perfs. POH 15 jts. WOC. SDFN.

FINAL REPORT - WELL P & A, 10/5/83.

Perf'd 4 holes @ 1140', spotted 30 sx cmt & squeezed 20 sx thru perfs.

Perf'd 2 holes @ 164', spotted 30 sx cmt leaving csg full of cmt. Cut wellhd off & installed DH marker.