

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

1-149-14-7663

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_

Lease No. \_\_\_\_\_

Chimney Rock

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

RECEIVED  
DEC 16 1957  
U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 9, 19 57

Well No. 2 is located 660 ft. from N line and 660 ft. from E line of sec. 15

NE NE Sec. 15  
(1/4 Sec. and Sec. No.)

31N  
(Twp.)

17W  
(Range)

NMPM  
(Meridian)

Wildcat  
(Field)

San Juan  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 5257 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

12-6-57. TD 948'. Ran 23 jts. 5 1/2" OD. 15.5#/ft. J-55 casing (941.00') set @ 948' with 50 sks. reg. cement, 50 sks. Formix, 4% gal. 1/4# Floccin/sack. Held 1000# for 30 min. Top of cement by temperature survey @ 350'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Products Company

Address P. O. Box 1565

Farmington, New Mexico

ORIGINAL SIGNED BY: JOHN J. STROJER

By \_\_\_\_\_

Title Petroleum Engineer

