

(SUBMIT IN TRIPLICATE)

Approval expires 12-31-60.

Indian Agency Ute Mountain

Tribe

Allottee Ute "A"

Lease No. 14-20-604-80

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Report of Setting of Liner</u>	<input checked="" type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 8, 1958

Well No. 2 is located 1980 ft. from S line and 1980 ft. from W line of sec. 8

NE/4-SW/4 Section 8
(¼ Sec. and Sec. No.)

31N
(Twp.)

14W
(Range)

N.M.P.M.
(Meridian)

Verde Gallup - Est.
(Field)

San Juan
(County or Subdivision)


New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 4177 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run & set 5" OD liner at 2999' w/Brown Oil Tool type CR liner hanger at 2996'. Liner slotted from 2524-99' w/408 1/2" x 1/2" slots. Liner is strong & is not to be cemented.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SEELY OIL COMPANY

Box 426

Address Farmington, New Mexico

By (Signed) P. E. Cosper

Title District Superintendent