UNITED STATES PEPARTMENT OF THE INTERIOR BEOLOGICAL SURVEY

GEOLOGICAL SURVEY	
	6. IF INDIAN, ANDTHE ORTHIBE NAME UTE MOUNTAIN INDIAN
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME UTE INDIAN
1. oil 🕱 gas uell other	9. WELL NO.
2. NAME OF OPERATOR W.M. Gallaway	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR 101-02 Petr. Plaza Bldg. Farmington, N.M.	VERDE GALLUP 11. SEC., T., R., M., OR BLK, AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA SEC. 10, T31N, R15W
below.) AT SURFACE: 2150' FSL 2010' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	SAN JUAN N.M.
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF	5724 V F I D
FRACTURE TREAT	
SHOOT OR ACIDIZE	8 NOTE: Report results of multiple completion or zone
OLL OR ALTER CASING	change on rorm 5-330.)
CHANGE ZONES	SURVEY
ABANDON* DURANGO, CO	LO. /
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen 4/18/81 Fill hole with gel water. Circulate w plug (17 sks.) over Gallup perf 1896 csq. rig down and moved.	irectionally drilled, give subsurface locations and it to this work.)* /45 tubing sub spotted cement
6/1/81 Tagged cement 1781' inside 5½" csq.,	across stub (15 sks), spotted of point lookout 450' to 550', cross bottom of surface csq.,
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	•
	DATE 8/14/81
(This space for Federal or Etate office APPROVED BY TITLE AREA MANA(CONDITIONS OF APPROVAL, IF ANY:	F.E. 2000

*See Instructions on Reverse Side

MAR 2,71986 OIL CON. DIV. DIST. 3

16,000 50