

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. MM 000260  
Unit Mexico - Fed #1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>DST No. 1 &amp; 2</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 18, 1961

Mexico Fed #1

Well No. 1 is located 1850 ft. from S line and 1850 ft. from W line of sec. 12

SW/4 Sect. 12  
(1/4 Sec. and Sec. No.)

MM  
(Twp.)

13W  
(Range)

N 100° E  
(Meridian)

Basin - Dakota  
(Field)

San Juan  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs; cementing points, and all other important proposed work)

TD 6875'


Drill Stem Test No. 6785-6875' Fourth Dakota

Packer failed.

Pulled test.

Drill Stem Test No. 2 6795 - 6875'. Fourth Dakota.

2" top choke and 3/4" bottom hole choke. Tool open 2 hours, opened with weak blow of air, increasing to fair blow in 10 minutes and continued throughout test. Very slight amount of gas to surface in 45 minutes. Recovered 270' of slightly gas cut mud. No water. 30 minute ISIMP 2770#. 30 minute PSIMP 1600#. ITP 195#. TTP 290#. Hydrostatic pressure in 3463#, out 3440#.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shelly Oil Company

Address Drauer 510

Farmington, New Mexico

By \_\_\_\_\_

(ORIGINAL) H. E. SAW

Title District Superintendent

12

1. The first part of the document is a list of the names of the persons who were present at the meeting. The names are listed in alphabetical order.

2. The second part of the document is a list of the topics that were discussed at the meeting. The topics are listed in alphabetical order.

3. The third part of the document is a list of the actions that were taken at the meeting. The actions are listed in alphabetical order.

4. The fourth part of the document is a list of the persons who were responsible for the actions that were taken at the meeting. The persons are listed in alphabetical order.

5. The fifth part of the document is a list of the persons who were responsible for the actions that were taken at the meeting. The persons are listed in alphabetical order.

6. The sixth part of the document is a list of the persons who were responsible for the actions that were taken at the meeting. The persons are listed in alphabetical order.

7. The seventh part of the document is a list of the persons who were responsible for the actions that were taken at the meeting. The persons are listed in alphabetical order.

8. The eighth part of the document is a list of the persons who were responsible for the actions that were taken at the meeting. The persons are listed in alphabetical order.

9. The ninth part of the document is a list of the persons who were responsible for the actions that were taken at the meeting. The persons are listed in alphabetical order.

10. The tenth part of the document is a list of the persons who were responsible for the actions that were taken at the meeting. The persons are listed in alphabetical order.

11. The eleventh part of the document is a list of the persons who were responsible for the actions that were taken at the meeting. The persons are listed in alphabetical order.