

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir
Use "APPLICATION FOR PERMIT - " for such proposals

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

14-20-600-3530

6. If Indian, Allottee or Tribe Name

NAVAJO TRIBAL

7. If Unit or CA, Agreement Designation

MANY ROCKS GALLUP UNIT

8. Well Name and No.

12

9. API Well No.

30-045-10903

10. Field and Pool, or exploratory Area

Many Rocks GA

11. County or Parish, State

SAN JUAN

NM

SUBMIT IN TRIPLICATE

070 FARMINGTON, NM

1. Type of Well

☒ Oil Well

☐ Gas Well

☐ Other

PK Petroleum

2. Name of Operator

MOBIL PRODUCING TX & NM INC.*

*MOBIL EXPLORATION & PRODUCING US INC. AS AGENT FOR MPTM

3. Address and Telephone No.

P.O. Box 633, Midland TX 79702

(915) 688-2585

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SEC. 8, T31N, R16W

(NE/SW) 1650' FSL & 1650' FWL

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐

Notice of Intent

☐

Subsequent Report

☒

Final Abandonment Notice

TYPE OF ACTION

☒

Abandonment

☐

Recompletion

☐

Plugging Back

☐

Casing Repair

☐

Altering Casing

☐

Other

P&A

☐

Change of Plans

☐

New Construction

☐

Non-Routine Fracturing

☐

Water Shut-Off

☐

Conversion to Injection

☐

Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SEE ATTACHED PLUG & ABANDON PROCEDURE (11-23-98 -- 11-24-98).

RECEIVED
DEC 18 1998

OIL CON. DIV.
DIST. 2

14. I hereby certify that the foregoing is true and correct

Signed

Shirley Houchins

Title

SHIRLEY HOUCHINS, ENV & REG TECH

Date

12-10-98

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

ACU

JRD

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

* See Instruction on Reverse Side

NMOCD

FA

GTON DISTRICT OFFICE

DEC 16 1998

ATTACHMENT - FORM 3160-5
MANY ROCKS GALLUP UNIT-WELL #12
APT # 30-045-10903
14-20-600-3530
NAVAJO TRIBAL
SAN JUAN COUNTY, NEW MEXICO

- 11-23-98 MIRU KEY ENERGY RIG #8, STAB RANIGAN (ROD BOP), UNSET PUMP, HOLD SAFETY MEETING. MIRU HOT OIL TRUCK, PUMP WTR DN TBG & CUT CSG & TBG ANNULUS, CIRC. PARAFIN OUT OF WELL, POOH W/RODS, ND WH, NU BOP, POOH W/TBG, PERF SUB, SN, PKR W/BULL PLUG (NOT A TAC). MIRU WL TRUCK, RIH W/JUNK BASKET, TO 1400', RIH & SET CIBP @ 1400', POOH W/WL, RIH TO CIBP W/TBG, NU CMT TRUCK, PRESSURE TEST CSG TO 525 PSI, TEST GOOD, PUMP 6 BBLS BALANCE PLUG OF 15.6#/GAL CMT F/1400-1022', POOH W/ 2 3/8" TBG TO 1022', CIRC. 13 BBLS PKR FLUID TO 110' POOH LD TBG. SI & SDFN. JONNEY BENNETT W/NAVAJO EPA & JOE SANCHEZ W/BLM WERE ON SITE.
- 11-24-98 DIG OUT AROUND WH, CHANGE OUT BRADEN VALVE, NU FLOW LINES. RIH W/WL TO 220', PERFORATE 4 1/2" CSG F/220-221' @ 3 SPF, POOH W/WL NU CMT TRUCK & CIRC FW DN CSG & UP OPEN HOLE ANNULUS. CMT DENSITY WAS 15.8 PPG. A TOTAL OF 53 SXS CMT USED TO PUMP SURFACE PLUG. CMT TO SURFACE. ND BOP, DIG OUT AROUND WH, CUT OFF WH & CSG APPROX 3' BELOW SURFACE. BREAK ROCK TO EXPOSE CSG. RDMO KEY ENERGY RIG #8. WELL PLUGGED & ABANDONED.

*11:00 AM 12-04-98 INSTALLED STEEL ID PLATE