


(SUBMIT IN TRIPLICATE)

Indian Agency Ute-Indian



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____
Lease No. Tribal No.
11-80-151-16

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 27, 1956

Ute-Indian 2

Well No. 1 is located 2000 ft. from N line and 2130 ft. from E line of sec. 10

SW/4E, Section 10
(1/4 Sec. and Sec. No.)

T-11-N, R-15-W
(Twp.) (Range)

N.T.P.M.
(Meridian)

Wildcat
(Field)

San Juan
(County or Subdivision)


New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5710 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

TD 1951'. Set 1947' of 5 1/2" casing at 1951' with 50 sacks cement. Drilled cement plug September 17, 1956. Subbed hole dry. Tested for 2 hours with 500 lbs. pressure, pipe OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ARTZ OIL & GAS COMPANY

Address P.O. Box 786

Farmington, New Mexico

By Joe C. Salmon
Joe C. Salmon
Title Drilling Superintendent

