

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **Santa Fe**  
Lease No. **078389**  
Unit

**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

XX

INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA

March 5

19 63

Lucerne

Well No. **4-A** is located **1714** ft. from **N** line and **970** ft. from **E** line of sec. **10**

**NE/4 Section 10**

**31-N**

**10-W**

**N.M.P.M.**

**Blanco Mesa Verde**

**San Juan**

**New Mexico**


The elevation of the derrick floor above sea level is **6101** ft.

**DETAILS OF WORK**

State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mud logs, and all other important proposed work.

On 1-29-63, this well was plugged and abandoned in the following manner:

1. Spotted a 20 sacks cement plug across perfs (5050' - 5238')
2. Shot 4 1/2" casing @ 4050'. Spotted a 20 sack cement plug on stub.
3. Spotted a 20 sack cement plug in surface w/a 4' x 4" dry hole marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Company**

Address **Box 990**

**Farmington, New Mexico**

By

Title **Petroleum Engineer**