



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R359.4
Approval expires 12-31-60.

Indian Agency San Juan

Allottee

Lease No. 24-00-000-0004

Co. San Juan

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Survey Table of

Farmington, San Juan

May 11, 1959

Well No. 27 is located 2000 ft. from N line and 2000 ft. from E line of sec. 20

SW 1/4 of SW 1/4 Sec. 20

San Juan

(Twp.)

(Range)

(Meridian)

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 5000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Spudded 7" hole 4/22/59. Set 7" casing at 40'. Drilled plug at 10:00 A.M., 4/22/59. Drilled water to 922' (4-1/2" hole) and mudbed up at 922'. San Juan. Log. Set 4" casing at 922' w/70 sacks of 40 lb cement. Pumped plug down w/200 sacks. San and oil. 10-922'. 100 922'. San Juan May 4 6:00 AM. Pumped 4" casing from 922' to 922' w/2 jet shots per foot. Sand/oil fractured w/20,000 gals. 100. crude and 50,000' sand. Ave. injection rate 17.6 gpm at 1200'. Cleaned sand from 922' to 922'. Set 2" tubing at 922'. San pump and rods and set pumping unit. On final 24 hour test on 12-20" SAN pumped 60 bbls. San oil. San 400. Crude. Crude. 30-2. First new oil produced to tanks May 2, 1959.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Juan Oil & Refining Company

Address San Juan

Farmington, San Juan

COPY SIGNED R. M. LILLY

By Donald E. Lilly

Title District Superintendent