


(SUBMIT IN TRIPLICATE)

Indian Agency _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. _____




SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 20, 1962

Well No. **29** is located **130** ft. from **N** line and **24** ft. from **E** line of sec. **7**
SW 1/4 Section 7 **23** **20** **1962**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian) (State or Territory)
(Field) (County or Subdivision)




The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

29 720.

Well was plugged and abandoned as follows: 2 1/2" plug in surface which covers top of casing annulus. A regulation dry hole marker was placed in top of cement. Ignition was checked and is ready for inspection.



U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Marble Oil and Refining Company**
P. O. Box 3000

Address **Paraguay, Colorado**

By **COPY (ORIGINAL SIGNED) B. M. BRADLEY**

Title **State Geologist**

10/10/1914

RECEIVED

10/10/1914

RECEIVED

10/10/1914

RECEIVED

RECEIVED
10/10/1914

RECEIVED
10/10/1914