

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

14-20-600-3530

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo - Ute Mountain

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Injection	7. UNIT AGREEMENT NAME Many Rocks Gallup Unit
2. NAME OF OPERATOR Atlantic Richfield Company	8. FARM OR LEASE NAME Many Rocks Gallup Unit
3. ADDRESS OF OPERATOR 501 Lincoln Tower Bldg., 1860 Lincoln St., Denver, Colorado	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit "M" - 330' f/South & 330' f/West lines Sec. 6	10. FIELD AND POOL, OR WILDCAT Many Rocky Gallup
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 6-31N-16W
15. ELEVATIONS (Show whether DE, RT, OR etc.) 5309'	12. COUNTY OR PARISH San Juan
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

Resume Injection

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING


ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was a producing well in the Many Rocks Gallup Unit until June 1964, at which time it was converted to a water injection well, injecting into Gallup perms 1180-88' and 1299-1305'. Due to decline in Unit oil production, in an effort to reduce operating expenses and to evaluate the Unit performance without injection, this well was shut in March 29, 1973. Cumulative injection is 765,366 BW into perms 1299-1305' and 850,768 BW into perms 1180-88'.

Propose to resume injection into Well No. 1, injecting approx 15 BWPD, and observe (pump test occasionally) Well #3 which is open in both the Upper and Lower Gallup sections. Well #3, Unit C (NE NW) Sec. 7, currently is a shut in oil well, being shut in 7/1/72 due to low production.



18. I hereby certify that the foregoing is true and correct

SIGNED

W. A. Walther, Jr.

TITLE

Operations Manager

DATE

6/8/76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side