


(SUBMIT IN TRIPLICATE)

Indian Agency Isosle



UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_

Lease No. \_\_\_\_\_

Site Contract  
11-00-1 1-1-5

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 21, 1959, 19\_\_\_\_

Use-Location

Well No. 1-8 is located 2020 ft. from [N] line and 1940 ft. from [E] line of sec. 1

34/36, Section 1  
(1/4 Sec. and Sec. No.)

1-321  
(Twp.)

1-170  
(Range)

N. 2. 2. 1.  
(Meridian)

Oil/Coal

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was originally to test Gallup formation.

Later decided to test Dakota formation.

6 1/2" hole was drilled from Gallup formation to a total depth of 2670'

ILLEGIBLE



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Autec Oil and Gas Company

Address Box # 736,

Paria, New Mexico

By ORIGINAL SIGNED BY JOE C. SALMON  
Joe C. Salmon

Title District Superintendent

