

(SUBMIT IN TRIPLICATE)

Indian Agency USAUNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY11-20-60-1947

Allottee _____

Lease No. 11-20-60-1947

Section 3

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL..... Intend to temporarily abandon	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 7


19 58

Well No. 6#1 is located 2310 ft. from 11-11 line and 1650 ft. from 16-11 line of sec. 311-11, SW 1/4, Sec. 3
(1/4 Sec. and Sec. No.)11-11 16-11
(Twp.) (Range)11-11
(Meridian)Undesignated
(Field)San Juan County
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 5608 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Notice is hereby given of intention to temporarily abandon the Hava Jo-Ute 6#1. The tubing will remain in the well with a valve on top of tubing.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Standard Oil Company of TexasAddress P.O. Box 1561Perdington, New MexicoBy Charles H. LantryTitle Field Foreman

