

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)


Name of Company Beaver Lodge Oil Corporation				Address 1101 Mercantile Dallas Building, Dallas, Texas			
Lease BLOC Marcotte #1	Well No. 1	Unit Letter E	Section 5	Township 31N	Range 10W		
Date Work Performed 6/25/59	Pool Blanco Mesaverde			County San Juan			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☐ Other (Explain):
☐ Plugging ☒ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Pulled tubing, set whipstock at 4312. Drilled through Mesa Verde section to Mancus shale. Set 4 1/2" pipe, perforated and fraced. Cleaned out hole, ran tubing and prepared for production test.



Witnessed by Melvin Cornell	Position Consultant	Company
---------------------------------------	-------------------------------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D 5008	P B T D	Producing Interval 4446 - 4974	Completion Date 7/8/59
Tubing Diameter 2 1/2	Tubing Depth 4907.11	Oil String Diameter 4 1/2"	Oil String Depth 5008	
Perforated Interval(s) 4874 - 4974, 4446 - 4496, 4516 - 4532				
Open Hole Interval			Producing Formation(s) Mesa Verde	

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover	In progress					

OIL CONSERVATION COMMISSION

Approved by
Original Signed Emery C. ArnoldTitle
Supervisor Dist. # 3Date
AUG 7 1959

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name

Position

Company