UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	14-20-603-2033
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Navajo
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
1 -11	8. FARM OR LEASE NAME
1. oil ☑ gas ☐ other	Navajo Tribe of Indians G
2. NAME OF OPERATOR	9. WELL NO.
Hicks Enco, Inc.	212
3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Many Rocks
2313 Santiago, Farmington, New Mexico, 87401	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.)	Sec.1 - 31N - 17W
AT SURFACE:	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: 2305 FNL, 2235 FEL AT TOTAL DEPTH:	San Juan News Mexico
	14. API NO.
 CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5334
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone
MULTIPLE COMPLETE	change on Form 9–330.)
CHANGE ZONES	
ABANDON* X	
(Other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent 5-23-78	all pertinent details, and give pertinent dates, rectionally drilled, give subsurface locations and to this work.)*
Spotted 15 sack plug 1316' - 1134'	
Circulated 4½ casing through leak at approximately sacks cement. Left 4½ casing and casing annual	nately 300' with 125 ulus full of cement.
Subsurface Safety Valve: Manu. and Type	5 gr @ Ft.
18. I hereby certify that the foregoing is true and correct SIGNED TITLE PRESIDENT	
- No Hicks	
(This space for Federal or State of co	e use)
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	JUN 1 1979
nmac	U. S. GEOLOGICAL SURVEY