

APPROVED **JAN 12 1955**
[Signature]
 ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY

Land Office **Santa Fe**
 Lease No. **678057 078507**
 Unit **San Juan 32-9**
14-08-001-569

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 11, 1955

Well No. **3** is located **1190** ft. from **[N]** line and **820** ft. from **[W]** line of sec. **1****NE 1/4 Section 1**
(1/4 Sec. and Sec. No.)**31N**
(Twp.)**10W**
(Range)**R4PM**
(Meridian)**Blanco**
(Field)**San Juan**
(County or Subdivision)**New Mexico**
(State or Territory)The elevation of the derrick floor above sea level is **6704** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

On January 3, 1955 moved over well with company tools. Pulled tubing and cleaned out to total depth of 6005'. Rerun 2" NUE tubing and set it at 5943'. Shut in well for tie on to gathering system January 7, 1955.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Company**Address **Box 997****Farmington, New Mexico**

ORIGINAL SIGNED J. F. TADLOCK

By _____

Title **Petroleum Engineer**