


(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 14-30-403-3074



ILLEGIBLE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF. <u>MAR 12 1959</u>
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING. <u>GEOLOGICAL SURVEY</u>
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR. <u>NEW MEXICO</u>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	<u>Subsequent Report of Perforating & Fracture Treatment</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Farlington, New Mexico March 20, 1959

Navajo Tribe "P"

Well No. 3 is located 640 ft. from S line and 1900 ft. from E line of sec. 4

3 1/4 of 36/4, Sec. 4
(1/4 Sec. and Sec. No.)

12-11
(Twp.)

17-14
(Range)

(Meridian)

Chimney Rock Gallup
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)


The elevation of the derrick floor above sea level is 5342 ft. 07.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

3/1/59: Van logs. Perforated from 1014' to 1030' w/2 jet shots per foot. Sand/13 fr stored w/20,000 gals. loose crude and 30,000' sand. Ave. inj. rate 17 bbls./min. @ 1200psi.

3/2/59: Set 2" tubing at 1021'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company

Address Box 1268

Farlington, New Mexico

By J. C. Kinley

Title Agent