

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYIndian Agency **Navajo**

Allottee

Lease No. **21-22-42-2024**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Navajo Tribe**Paradise, New Mexico****July 21, 1959**

Well No. **37** is located **640** ft. from **N** line and **1200** ft. from **E** line of sec. **4**
SW 1/4 of SW 1/4 Sec. 4 **T-21-N** **R-17-W** **ZONE**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Chimney Rock Gallup **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5211** ft. **Gr.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 7-2/3' hole 7/21/59. Set 7" casing at 25' w/o casing seg. cement.
Drilled w/air to 1200' & mudded up. Drilled to 13 of 1150'. Run elec. logs.
No show in Gallup.

7/22/59: Received permission from the United States Geological Survey to plug
and abandon. To set 25 casing seg. cement plug in bottom, top cement plug, and
place marker.

Now preparing to abandon.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Shutle Oil & Refining Company**Address **Box 1260****Paradise, New Mexico**By **J. C. Stanley**Title **Agent**

		X	

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency **Navajo**
Allottee _____
Lease No. **14-22-403-3024**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED
AUG 6 1959

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Navajo Tribe "F"

Farmington, New Mexico August 3, 1959

Well No. **37** is located **660** ft. from **[N]** line and **1980** ft. from **[E]** line of sec. **4**
NE 1/4 of NE 1/4 Sec. 4 T-31-N R-19-W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Quinay Rock Galling San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **9311** ft. **(w.)**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Placed cement plug from 1135' to 1035' w/25 sacks reg. cement. Set top plug in 7" casing w/7 sacks reg. cement. Installed abandonment marker. Final report for well 7/24/59.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Shumble Oil & Refining Company**
Address **Box 1268**
Farmington, New Mexico

By **COPY ORIGINAL SIGNED: R. M. LILLY**
Amos H. Lilly
Title **Agent**