



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa FeLease No. 070472Unit Sun Juan 32-7

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Water Frac.</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 15, 1959

Well No. 22-25 (ND) is located 1130 ft. from (N) line and 1550 ft. from (E) line of sec. 25SW/4 Sec. 25
(1/4 Sec. and Sec. No.)32S
(Twp.)17E
(Range)10N
(Meridian)Blanco M.V. & Wilcox Bas.
(Field)Sun Juan
(County or Subdivision)N.M.
(State or Territory)The elevation of the derrick floor above sea level is 6312 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9-3-59 Total Depth 7966'. C.O.T.D. 7966'. Water fractured lower Dakota perf. 7858-7881; 7913-7925 (w/2 Super DJ/ft.) w/55,200 gal. water & 21,500 gal. sand. ND pr. 2900%, max. pr. 4300%, avg. tr. pr. 4100%. I.R. 30.4 BHM. Flush 17,000 gallons. Spotted 200 gal. MCA before perforating. 1 1/2 CaCl in all frac. water.

9-6-59 Total Depth 8015'. Temporary bridge plug at 7858'. Water fractured upper Dakota perf. Int. 7794-7804; 7816-7824; 7832-7840 (w/2 Super DJ & 2 Torpedo jets/ft.) w/49,391 gallons water & 21,000 gal. sand. ND pr. 3700%, max. pr. 4500%, avg. tr. pr. 4100%. I.R. 41.3 BHM. Flush 2700 gallons. Spotted 160 gal. MCA before perforating. Frac water contained 1 1/2 CaCl.

9-12-59 Total Depth 7966'. Temporary bridge plug at 7725'. Water fractured Mesa Verde perf. Int. 5308-52; 5344-54; 5416-50; 5426-34; 5530-35; 5530-44; 5546-36; 5560-67; 5570-75; 5580-84; 5587-92; 5596-9602; 5627-31; 5636-40 (2 DJ/ft.) w/100,000 gallons water & 30,000 gal. sand. ND pr. 1100%, max. pr. 2700%, avg. tr. pr. 1800%. I.R. 25 BHM. Flush 10,000 gallons. Dropped 7 sets of 10 balls each.

Company El Paso Natural Gas CompanyAddress Sun JuanFarmington, New MexicoORIGINAL SIGNED H.E. McANALLY
By _____Title Petroleum Engineer