

P O Box 1980, Hobbs, NM

District II

P O. Drawer DD, Artesia, NM 88211

District III

1000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION DEPUTY OIL & GAS INSPECTOR OFFICE

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO

APPROPRIATE

DISTRICT OFFICE

AND 1 COPY TO

AS DIRECTOR OFFICE

SEP 15 1995

PIT REMEDIATION AND CLOSURE REPORT

Operator: Phillips Petroleum Company **Telephone:** (505) 599-3460

Address: 5525 Hwy. 64, NBU 3004, Farmington, NM 87401

Facility Or: San Juan 32-8 Unit #30

Well Name

Location: Unit or Qtr/Qtr Sec SW SW **Sec**27 **T**32N **R**8W **County**San Juan

Pit Type: Separator ☒ Dehydrator ☐ Other ☐

Land Type: BLM ^X, State _____, Fee _____, Other _____

Pit Location: Pit dimensions: length 15', width 19', depth 1'
(Attach diagram)

Reference: wellhead_x , other

Footage from reference: 85'

Direction from reference: 30 Degrees _____ East North _____
of
X West South X

Depth To Ground Water: Assume (50' Less than 50 feet (20 points)
(Vertical distance from for strictest 50 feet to 99 feet (10 points)
contaminants to seasonal standards Greater than 100 feet (0 Points) 20
high water elevation of
ground water)

Wellhead Protection Area:
(Less than 200 feet from a private domestic water source, or; less than 1000 feet from all other water sources)

RECEIVED
MAY - 9 1994
OIL CON. DIV.
DIST. 3

Yes (20 points)
X No (0 points) 0

Distance To Surface Water:
(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches)

Less than 200 feet	(20 points)	
200 feet to 1000 feet	(10 points)	
Greater than 1000 feet	(0 points)	0

RANKING SCORE (TOTAL POINTS): 20

Date Remediation Started: n/a Dated Completed: _____

Remediation Method: Excavation _____ Approx. cubic yards _____
(Check all appropriate sections) Landfarmed _____ Insitu Bioremediation _____
Other _____

Remediation Location: Onsite _____ Offsite _____
(ie. landfarmed onsite, name and location of offsite facility)

General Description Of Remedial Action: n/a

Initial assessment of pit showed soils to be clean

at the surface and at three feet below pit bottom.

Ground Water Encountered: No ☒ Yes _____ Depth _____

Final Pit: Sample location deepest part of pit. Sampled with a backhoe.

Closure Sampling:
(if multiple samples, attach sample results and diagram of sample locations and depths)

Sample depth 3' below pit bottom

Sample date 7/12/93 Sample time _____

Sample Results

Benzene (ppm) -

Total BTEX (ppm) -

Field headspace (ppm) 0.8

TPH 10.1

Ground Water Sample: Yes _____ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 4-13-94

SIGNATURE Ed Hasely

PRINTED NAME Ed Hasely
AND TITLE Environmental Engineer

1993

ENVIROTECH, INC.

PIT NO	WELL NAME	U.S.F.H.	PIT TYPE	RANK SCORE	CLOSURE STANDARD TPH (PPM)	DATE 1993	ORGANIC MATERIALS EXTRACTED Sub-Surf. Depth	SOIL TYPE	PIT TYPE	SAMPLE NO.	Organic Vapor Mater. (ppmv)	Total Recoverable Pet. Hydro. (PPM)	EPA METHOD 8020 (PPB) METHOD 5030 PURGE-AND-HEAT				TOTAL BTEX	STATUS
													Benzene	Toluene	Ethyl Benzene	Xylene		
PA039	SAN JUAN 29-6, #95	M272906	SEP	0	5000	7-09	NO	SM	EARTHEN	T1-7 T1-13 T1-17	533 423 87	9.1	0	67	0	27	94	TEST
PA040	SAN JUAN 29-6, #43-26	G262906	SEP	10	1000	7-09	NO	SC	EARTHEN	T1-8	0	0						CLOSE
PA041	SAN JUAN 29-6, #98	M262906	SEP	10	1000	7-09	NO	CL	EARTHEN	T1-7.5	1.2	7.5						CLOSE
PA042	SAN JUAN 32-8, #15	M243108	SEP	0	5000	7-12	NO	SC	EARTHEN	T1-3.5 T1-6	0.5 1.1	8.8						CLOSE
PA043	SAN JUAN 32-8, #20 NP	L043108	SEP			7-12	NO	SM/CL	EARTHEN	T1-1.5 T1-4	0.8 0.8	0						CLOSE
PA044	SAN JUAN 32-8, #25-31	B333208	SFP			7-12	NO	SM/SC	EARTHEN	T1-1 T1-4	0.5 0.8	13.5						CLOSE
PA045	SAN JUAN 32-8, #30-27	M273208	SEP			7-12	NO	SM	EARTHEN	T1-1.5 T1-4	0.8 0.8	10.1						CLOSE
PA046	SAN JUAN 32-7, #58	G183207	SFP			7-12	NO	OH/CL	EARTHEN	T1-5 T1-7 T1-13 T2-6 T2-11 T2-13	1856 691 100 2.1 1.1 1.1	68						REM
PA047	SAN JUAN 32-7, #43	B213207	SEP	20	100	7-12	NO	OH/CL	EARTHEN	T1-5 T1-10	229 2.8	9.1						TEST
PA048	SAN JUAN 32-7, #5	H083107	SEP	20	100	7-12	NO	SM	EARTHEN	T1-2.5 T1-5	1.1 0	0						CLOSE
PA049	SAN JUAN 32-7, #5	H083107	BLOW	20	100	7-12	NO	SP	EARTHEN	T1-3.5	0	335						REM
PA050	SAN JUAN 29-5, #106 PM	K252905	SEP	0	5000	7-13	NO	CL/GM/SM	EARTHEN	T1-7 T1-10 T2-5 T2-11	607 617 5 18.6	610						TEST
PA051	SAN JUAN 30-5, #4	B353005	SEP	10	1000	7-13	NO	OL	EARTHEN	T1-1.5 T1-4	2 2.4	17.1						CLOSE
PA052	SAN JUAN 30-5, #11	L233005	SEP	10	1000	7-13	NO	SM	EARTHEN	T1-5	14	6.5						CLOSE
PA053	SAN JUAN 30-5, #32-26	A263005	SEP	0	5000	7-13	NO	SM	EARTHEN	T1-4	1.3	17.1						CLOSE
PA054	SAN JUAN 30-5, #8-11	B113005	SEP	10	1000	7-13	NO	SC	EARTHEN	T1-0.5 T1-3	0 0	5.6						CLOSE

FILE NO: PA045

C.E.C. NO: 2816

JOB No: 93163
PAGE No: 1 of 1

DATE STARTED: 7-12-97
DATE FINISHED: 7-12-97
ENVIRO. SPCLT: RED
OPERATOR: CIMARRON
ASSISTANT:

LAND USE: RANGE - LEASE SF 079717

SURFACE CONDITIONS: EARTHEN PIT - CRT W. DEAD WEEDS

FIELD NOTES & REMARKS: PIT IS LOCATED APPROXIMATELY 85 FEET S.30°W. OF WELLHEAD.
CLOSURE STD: — WELL CLOSED-IN IN 1985.

RANKING SCORE:

T1: MOIST, BROWN, SAND, NO CLAY.
SILT


[illegible]

SCALE

15' x 19'

0 5 10 FEET

SITE DIAGRAM



TEST HOLE LOGS:

TH#:	SOIL TYPE	SMPL. DEPTH	DATE
1	PT 0.1		
2	SM 0.1	0.2	
3			
4	SM 0.1	0.2	
5	TD - 4'		
6			
7			
8			
9			
10			

1 - 20 = ps. 1 = Mon. 14 = Sat. 3 = Lang. 1 = Juver. English, 1 = Home, 1 = 21st. Working 2 = Priority, 4 = am.