



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa Fe
Lease No. 070268
Unit San Juan 32-9 Unit
14-03-001-569

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 6, 1958

Well No. 60 is located 1550 ft. from (N) line and 22 ft. from (E) line of sec. 23

NE	Sec. 23	32N	W	N.M.P.M.
(1/4 Sec. and Sec. No.)		(Twp.)	(Range)	(Meridian)
Blanco		San Juan		New Mexico
(Field)		(County or Subdivision)		(State or Territory)

The elevation of the derrick floor above sea level is 632 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

4-26-58. Total Depth 6195'.
Ran 44 joints 5 1/2", 15-50#, J-55 liner (2310') set from 3882' to 6192' with
100 sacks regular cement, 100 sacks Pozmix, 6% Gel, followed by 50 sacks
regular cement.

Held 1400# for 30 minutes.

Top of cement by temperature survey at 3950'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas CompanyAddress Box 927Farmington, New MexicoBy Original Signed F. H. W. P.Title Petroleum Engineer