



(SUBMIT IN TRIPPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY DIST 3

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office Santa Fe

Lease No. 078039

Min. Sec 26

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 19 63

Barnes
Well No. 1 is located 850 ft. from [N] line and 840 ft. from [E] line of sec. 26

NE 1/4 Sec 26 T-32-N R-11-W NMEM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Basin Dakota San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 6-3/4" hole below 7-5/8" casing to T. D. of 7785'. Ran 260 Jts. of 5 1/2" 15.5# J-55 casing landed @7742 W/Baker stage collar @3530'. Cemented 1st. stage w/75 sks. Po-mix cement and 2nd. stage w/100 sks Class C cement. Cement Bong log indicated Tops @ 7000' and now waiting on completion rig.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Delhi-Taylor Oil Corp.

Address P. O. Box 1198

Farmington, N. M.

Original signed by
By A. R. Gibson
Title Dist. Supt.