



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office SF
Lease No. 076507
Unit San Juan 32-2 Unit
14-08-001-569

SUNDRY NOTICES AND REPORTS ON WELLS
RECEIVED

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Water Frac.</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 8, 1957

Well No. 50 is located 550 ft. from $\begin{Bmatrix} N \\ S \end{Bmatrix}$ line and 1150 ft. from $\begin{Bmatrix} E \\ W \end{Bmatrix}$ line of Sec. 25

NE Sec. 25 (1/4 Sec. and Sec. No.) 32N (Twp.) 10W (Range) N.M.P.M. (Meridian)
Blanco (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6646 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

8-2-57 Total depth 5970'. Water frac. C. H. & P. L. perf. Int. 5422-5440; 5760-90; 5800-10; 5834-50; 5896-5916 w/2 SPT. w/88,000 gallons water and 80,000 sand. Breakdown pressure 1475#, max. pr. 3000#, I. R. 61 bbls/min. Flush 6000 gallons.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

By Original Signed D. C. Johnston

Title Petroleum Engineer