Form 9-881 a (Feb. 1981)					

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land	Office	Sinte	ı Pe	
Lease	No	9793	41	
Unit _	San	Juan	32-9	Unit
		nel no		

Address Box 997					
Towns 197 Theat Hadres	al Ges Compe	rgy			*********
I understand that this plan of wor			Geological Su	arvey before transform may be com	menced.
				OIL CON COM. DIST. 3	
Held 500#/30 minutes	•			RECEIVEN	
Spud date 6-21-59 On 6-22-59 Total dep Ran 10 joints, 13 3/6 sacks regular coment to the surface.	th 329'. 8", 48.00#,	H-40 casing	(310')	set at 321' with 210)
The elevation of the derric	Di	ETAILS OF W	ORK	roposed casings; indicate mudding	jobs, cement~
Bleaco M. V. & Wilde	et Dekota	San Juan ounty or Subdivision)		New Mexico (State or Territory)	
HE/4 Sec. 21 (¼ Sec. and Sec. No.)	32N (Twp.)	(Range)	H.M	feridian)	
Well No. 70(MD) is loca	ated 1563 ft.	from $\{N\}$ line	and 840	June 23 ft. from E line of se	,
(INDIC	CATE ABOVE BY CHECK	MARK NATURE OF RE	PORT, NOTICE	E, OR OTHER DATA)	
NOTICE OF INTENTION TO PULL OF NOTICE OF INTENTION TO ABANDO		l ij	1 11		
		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR. SUBSEQUENT REPORT OF ABANDONMENT.			
NOTICE OF INTENTION TO RE-DRIL	.L OR REPAIR WELL				
NOTICE OF INTENTION TO TEST WANTING OF INTENTION TO SHOOT		SUBSEQ		of Shooting or acidizing	