



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079341
Unit San Juan 32-2 Unit
14-00-001-569

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sept. 1, 1959

Well No. 70-1(ND) is located 1563 ft. from N line and 690 ft. from E line of sec. 21

NE 1/4 Sec. 21 32N 7E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco M.V. & Wildcat Oak. San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6212 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

8-1-59 T.D. 4003'. Ran 28 joints 9 5/8", M-80, 4000' casing (1098') & 76 joints 9 5/8", J-55, 36.00' casing (2930') for a total of 104 joints (3908') set at 4000'. Cemented with 120 sacks regular cement w/4% Gel, 1/4 cu. ft. fine Gilsomite/sk. followed by 50 sacks regular cement.
Top of cement by temperature survey at 3040'.
8-26-59 T.D. 6197'. Ran 24 joints 7", M-80, 26.00' casing (795') and 57 joints 7", M-80, 23.00' casing (2342') & 123 joints J-55, 23' casing (5046') for a total of 204 joints casing (6183') set at 6192', cemented with 980 sacks 50/50 Pozmix, 6% Gel, 1/4% Floccs/sk, 1/2% Fine-tuffplug/sk, followed by 50 sacks regular cement.
Top of cement by temperature survey at 3500'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 297
Farmington, New Mexico

RECEIVED
SEP 4 1959
OIL CON. COM.
DIST. 3
ORIGINAL SIGNED J.J. TILLERSON
By _____
Title Stratacon Engineer