٠.	 	 
-		
١	 	 
ļ		
1	 	 
1		
	:	
	•	1

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

	get Burcau roval expir		
	Sante	Fe	
Land Office			
Lease No.	07850	χŧ	<del></del>
Unit 14-0	Junn	32-9	Unit
14-0	( <del>-</del> CO1-	767	

S	SUNDRY I	NOTICES AN	D REPO	RTS ON	WELLS	
NOTICE OF INTENT	TION TO DRILL		SUBSEQUENT R	EPORT OF WATER S	HUT-OFF	
NOTICE OF INTENT	TION TO CHANGE PLA	.NS	SUBSEQUENT RI	EPORT OF SHOOTING	G OR ACIDIZING	
NOTICE OF INTENT	TION TO TEST WATER	SHUT-OFF	SUBSEQUENT RI	EPORT OF ALTERING	G CASING	
NOTICE OF INTENT	TION TO RE-DRILL OF	R REPAIR WELL	ll .		ING OR REPAIR	·-
		CIDIZE	SUBSEQUENT R	EPORT OF ABANDON	IMENT A	
		TER CASING	- 11		5 F 4 A	
NOTICE OF INTENT	TION TO ABANDON WI	ELL			<i>i.d.</i> <b></b>	
<u></u>	(INDICATE	ABOVE BY CHECK MARK NA	TURE OF REPORT, I	NOTICE, OR OTHER D	MATA)	NO.
				J	17.1010iil	, 19.57
Well No. 42	is located	d 900 ft. from	N line and		· .	
MR Se	c. 23	J	TON	n.M.P.N		
(1/4 Sec. and	Sec. No.)		ange)	(Meridian)		
Rlanc	I	San Juan (County or S	akilais-V		w Mexico (State or Territory)	
(Fiel	u.)	(County of 8	word floidill	•		
The elevation	of the derrick f	loor above sea level	is 6693 ft S OF WORK			
State names of and	expected depths to o	bjective sands; show sizes, ing points, and all othe	weights, and lengt	ths of proposed casi:	ngs; indicate muddi	ng jobs, cement
Fen 1 5974' follo feld Top o	with 125 es wed by 50 sa 1000g for 30 f cement by	1/2 , 15.5%, J- icks regular com icks regular com	ent, 125 a ent. vey at 351	o'.	201	commenced.
		must receive approval in wr	iting by the Geolo	gical Survey before	'operations may be o	commenced.
Address	вох 997					
	Farmington,	, New Mexico	В	yOriginal Sig	ned D. C. Jo	hns'on
			Tit	le Petrol	eum änginee	r