


Form 9-831a  
(Feb. 1961)

(SUBMIT IN TRIPLICATE)

Land Office Santa Fe  
Lease No. 072499-B  
Unit Allison Unit

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 31, 1958

Well No. 16 (20) is located 800 ft. from S line and 1800 ft. from W line of sec. 15


SW Sec. 15 22N 7W T.M.P.M.  
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
H. Los Pinos & Blanco San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6065 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud date 4-19-58.  
On 4-22-58. Total Depth 230'.  
Ran 7 jts. 13 3/8", 48#, J-55 casing (218') set at 228' with 150 sacks Neat cement, 1/8# Floccula/sk and 2# CaCl<sub>2</sub>, circulated to surface.  
Held 500# for 30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 937

Farmington, New Mexico

By Original Signed D. C. Johnston

Title Petroleum Engineer

1. The first part of the document discusses the importance of maintaining accurate records of all transactions. This is essential for ensuring the integrity of the financial statements and for providing a clear audit trail. The records should be kept up-to-date and should be easily accessible to all relevant parties.

2. The second part of the document outlines the various methods used to collect and analyze data. This includes the use of statistical techniques to identify trends and patterns in the data. It also discusses the importance of using reliable sources of information and the need to validate the data before using it for analysis.

3. The third part of the document describes the process of interpreting the results of the analysis. This involves comparing the findings with the expected outcomes and identifying any significant differences. It also discusses the importance of communicating the results clearly and concisely to the relevant stakeholders.

4. The fourth part of the document discusses the implications of the findings and the need for further research. It highlights the limitations of the current study and suggests areas for future investigation. It also emphasizes the importance of using the findings to inform decision-making and to improve the overall quality of the organization's operations.

5. The fifth part of the document provides a summary of the key findings and conclusions. It reiterates the importance of maintaining accurate records and the need for ongoing monitoring and evaluation. It also provides a final recommendation for the organization to continue to improve its financial management practices.