

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 076459-B
Unit Allison Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Water Frac.</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 16, 1958


Well No. 16 (MD) is located 890 ft. from S line and 1300 ft. from W line of sec. 15
SW Sec. 15 32N 7W N.M.P.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
H. Los Pinos & Blanco San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6866 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7-1-58. Total Depth 8490'. Temporary Bridge Plug at 6150'. Water fractured Point Lookout perforated intervals 6038-3058; 6072-6098; w/2 shots/ft with 58,000 gallons water and 60,000# sand. B.D.P. None, max. pr. 2800#, avg. tr. pr. 2200#. I.R. 50 B.P.M. Flush 6000 gallons.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 937

Farmington, New Mexico

By Original Signed D. C. Johnson
Title Petroleum Engineer

1. The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that proper record-keeping is essential for the transparency and accountability of the organization. This section also outlines the various methods used to collect and analyze data, ensuring that the information is reliable and up-to-date.

2. The second part of the document focuses on the implementation of the proposed changes. It details the steps involved in the process, from the initial planning stage to the final execution. This section highlights the challenges faced during the implementation and the strategies used to overcome them. It also provides a timeline for the completion of the project, ensuring that all stakeholders are aware of the progress.

3. The third part of the document discusses the results of the implementation. It presents the data collected and the analysis performed, showing the impact of the changes on the organization's performance. This section includes a comparison of the results with the initial goals, demonstrating the effectiveness of the proposed changes. It also identifies areas for further improvement and provides recommendations for future actions.

4. The fourth part of the document discusses the conclusions drawn from the study. It summarizes the key findings and the implications of the research. This section also provides a final assessment of the overall success of the project and the value added to the organization. It concludes by emphasizing the importance of continuous monitoring and evaluation to ensure the long-term success of the implementation.

