UNITED STATES



DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT	
Sundry Notices and Reports on Wells Philiph	
1. Type of Well GAS OTO AUG 2 4 1999 AUG 2 4 1999	5. Lease Number SF-079322 6. If Indian, All. or Tribe Name 7. Unit Agreement Name
2. Name of Operator	San Juan 32-9 Unit
BESOURCES OIL & GAS COMPANY OI	8. Well Name & Number San Juan 32-9 U#54 9. API Well No. 30-045-11432 10. Field and Pool Blanco Mesaverde 11. County and State San Juan Co, NM
Casing Repair Water Sh Final Abandonment Altering Casing Conversi X Other - tubing repair 7-27-99 MIRU. ND WH. NU BOP. TIH, tag up @ 6236'. TOOH w 7-28-99 TIH w/RBP, set @ 5320'. PT csg to 500 psi/15 min Repair csg. NU new tbg head, NU BOP. SDON.	truction ine Fracturing but off on to Injection 7/2-3/8" tbg. SDON. as. ND BOP, ND tbg head.
7-29-99 TIH & eng RBP. Blow well. Rls RBP & TOOH. TIH, C 2-3/8" 4.7# J-55 tbg, set @ 6176'. ND BOP. N 14. I hereby certify that the foregoing is true and correct. Signed Wallsa K Hebert Title Regulatory Administrator	U WH. RD. Rig released.
(This space for Federal or State Office use)	TLW
APPROVED BY Title Dat CONDITION OF APPROVAL, if any:	e FOR RECORD
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any departm United States any false, fictitious or fraudulent statements or representations as to any matter within its	