

(SCEMIT IN TRIPLICATE)

UNITED STATES - DEPARTMENT OF THE INTERIOR

Budget Buresu No. 42-R358.4. Form Approved.

Land Office Santa Fe

1cose No. 079322

Unit San Juan 32-9 Unit

SUNDRY NOTICES AND REPORTS ON WELLS

GEOLOGICAL SURVEY

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OF REPAIR WELL	SUBSFOUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDICE	SUBSEQUENT REPORT OF ABANDORMENT
NOTICE OF INTENTION 19 PUBL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
UNDICATE ABOVE BY CHACK MA	ON NATURE OF REPURE, NOTICE, OR OTHER DATA)
	June 19 , 1963
Well No. 11 is located 990 ft. fro	ni [N] line and 860 ft. from [E] line of sec. 14
NE/4 Section 14 32-N	9-W N.M.P.M.
(% three many of No.) (Twp)	· New Mexico
Blanco Mesa Verde San Juan	or Subdivision (State or Territory)
Const	
The elevation of the derrick floor above sea	evel is \$881 ft.
DET.	AILS OF WORK U.S. CECLORION OF
State names of and expected depths to objective sands; show	sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement———————————————————————————————————
ing points, and a	Construction proposed work)
On 5-15-63, this well was Plugged a	nd Abandoned in the following manner:
2. Cut 7" casing @ 1350". Spotted &	fill open hole (5763-6280'). Pulled tubing. O sack cement plug on 7" casing stub. ement plug in surface $w/4' \times 4"$ dry hole marker
	SULTYED \
<i>-</i>	
- · ·	1AY 1 7 1971
$\int r_{\rm M}$	CONLOOM
	in Gritale bOM eological Survey before operations may be commenced.
Company El Paso Natural Gas Company	V
Address Box 990	••
Farmington, New Mexico	By
	Title Petroleum Engineer