


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **079322**
Unit **San Juan 32-9 Unit**



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 19 **1963**

Well No. **11** is located **990** ft. from **N** line and **860** ft. from **E** line of sec. **14**

NE/4 Section 14
(1/4 Sec and 1/4 Sec No.)
Blanco Mesa Verde
(Field)

32-N **9-W**
(Twp) (Range)
San Juan
(County or Subdivision)

N.M.P.M.
(Meridian)
New Mexico
(State or Territory)

RECEIVED

The elevation of the derrick floor above sea level is **6881** ft.

JUN 11 1963


DETAILS OF WORK

U. S. GEOLOGICAL SURVEY

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 5-15-63, this well was Plugged and Abandoned in the following manner:

1. Spotted 150 sack cement plug to fill open hole (5763-6280'). Pulled tubing.
2. Cut 7" casing @ 1350'. Spotted 20 sack cement plug on 7" casing stub.
3. Pulled casing. Spotted 10 sack cement plug in surface w/4' x 4" dry hole marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Company**

Address **Box 990**

Farmington, New Mexico

By **Edward Sigurd E. H. WOOD**

Title **Petroleum Engineer**