

(SUBMIT IN TRIPLICATE)

Land Office Santa Fe  
Lease No. 079655  
Unit 3-1/2 Sec. 17UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 1, 1953

Well No. 4296 N. 17 is located 990 ft. from [N] line and 990 ft. from [E] line of sec. 17

NE 1/4 sec. 17 (1/4 Sec. and Sec. No.)      28 (Twp.)      10N (Range)      N. 100.0000 (Meridian)

Blanco (Field)      San Juan (County or Subdivision)      New Mexico (State or Territory)

The elevation of the ~~druck floor~~ <sup>ground</sup> above sea level is 6754 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 7" casing to bottom as follows: 1 Jt. 7" OD 23 J-55 STAG 12.75'.  
 23 Jts. 7" OD 23 J-55 STAG 3914.43'. 32 Jts. 7" OD 23 J-55 STAG 376.67'.  
 Total casing 53 3.45' set at 5320 RKB. Baker model 7 2 stage cementer set at  
 347' RKB. 1st stage cemented with 235 sac. regular cement. Pumped plug to  
 5272 RKB. Job completed 11:05 PM, 2-27-53. 2nd stage cemented with 150 sac  
 reg cement. Job completed 9:30 AM, 2-28-53. On March 9, 1953 tested casing  
 with 500# for 15 min., tested OK. Drilled cement plug at 5230 RKB, tested hole  
 with 500# for 15 min., tested OK.

U.S.G.S. - - - - 4  
 Region - - - - 1  
 District - - - - 2

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Phillips Petroleum CompanyAddress Box 939Santa Fe, New MexicoBy Earl SturmTitle District Superintendent