

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Form No. 42-R1421.

5. LEASE DESIGNATION AND SERIAL NO.

SF 078459-B

6. IF INDIAN ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use APPLICATION FOR PERMIT for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
El Paso Natural Gas Company

3. ADDRESS OF OPERATOR
PO Box 990, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface 1650'S, 825'E

7. UNIT AGREEMENT NAME
Allison Unit

8. FARM OR LEASE NAME
Allison Unit

9. WELL NO.
26 (MD)

10. FIELD AND POOL, OR NEIGHBOR
Blanco Mesa Verde
Basin Dakota

11. SEC. T. R. M. OR BLM. AND
SUCCESSION OR AREA
Sec. 9, T-32-N, R-7-W
NMPM

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6632'GL

12. COUNTY OR PARISH
San Juan
13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*


on 11-12-71, pulled 1 1/4" Mesa Verde tubing.

on 11-13-71, pulled 1 1/2" Dakota tubing, cleaned out to top of packer at 5909'.

on 11-14-71, redressed seal assembly and reran 256 joints 1 1/2", 2.9#, J-55 Dakota tubing, 8117' landed at 8126'. Reran 182 joints 1 1/4", 2.3#, J-55 Mesa Verde tubing, 5869' landed at 5879'. Returned well to production.



U. S. GEOLOGICAL SURVEY
DURANGO, COLO.



18. I hereby certify that the foregoing is true and correct

SIGNED Original Signed F. H. WOOD

TITLE Petroleum Engineer

DATE January 6, 1972

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

22