


SECTION 36



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

XXXXXX Navajo Tribal

Lease No. 14-20-0603-7116

Unit \_\_\_\_\_

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		Notice of intention to temporarily abandon	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 10, 1965

Tribal 21-36

Well No. 2 is located 1980 ft. from {N  
S} line and 660 ft. from {E  
W} line of sec. 36SE $\frac{1}{4}$  of NE $\frac{1}{4}$ , Sec. 36

31N

18W

NMPM

(¼ Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Undesignated  
(Field)San Juan  
(County or Subdivision)New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 5130 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The status of this well is the same as stated in our supplementary well history report dated May 22, 1964. We request approval to leave the well in the current status and temporarily abandon.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company STANDARD OIL COMPANY OF TEXAS, A Division of California Oil Company

Address 3610 Avenue S

Snyder, Texas

By R. E. Rigsby

Title Lead Drilling Engineer